

09/486549





Fig. 1 FIG. 1






FIG. 3

1 minute after ignition





FIG. 4


3 minutes after ignition

BEST AVAILABLE COPY



6 minutes after ignition

FIG. 5



12 minutes after ignition

FIG. 6




FIG. 7

17 minutes after ignition



FIG. 8

20 minutes after ignition

BEST AVAILABLE COPY